





If this harness exists?, you had factory A/C, day 1. if the A/C is not used now?, be sure to unplug the AMP or the ECU will have a false high IDLE.